

Plumbing Gobi Collectors Using Dyn-O-Seal Unions with Discs

Gobi Collectors are factory fitted with heavy brass half-unions for quick interconnection without soldering. The unions make a positive seal with any solar collector fluid. The O-rings, (two per collector), are to be inserted before tightening the mating half-

unions on the collectors. They are attached to the Gobi Frame in a plastic pouch.

Capping off and connecting feeder lines can be efficiently performed with the DOS Disk kit.

DOS Disc

Heliodyne's heavy-duty zero-clearance machined brass union is factory fitted to all collectors.

The DOS disc consists of the components listed to the left. Use this accessory to cap off the unused fittings on any collector array.

